
























US and Metric Thread Sizes

PRINTABLE FASTENER TOOLS SERIES

US Thread Sizes



Metric Thread Pitches



Scale Check: After printing, measure ruler above to ensure correct scale